3413-B Triplett Roll Chart

Supplement (To Roll Chart 84-71-080157-5)

TUBE TYPE	A Cir	KNOB: B Fil	S C Load	LEVER PO U Up	DSITION DOWN
00A 01A 0A2 (Good=10) 0B2 (Good=10) 0Y4 1A3 1A4 1A5 1A6 Tests 1-2 1A7 Tests 1-2 1AB5 1B4 1B4P (951) 1B5 (25S) 1B5 Tests 2-3 1B7 Tests 1-2 1C5 1C6 Tests 1-2 1C7 Tests 1-2 1C8 (Adapt BW) 1C21 1D3	2 4 4 1 1 2 2-1 1-1 1-1 2 1-1 1-1 2-1 2-1 2-1		30 45 40 95 22 75 28 50 50–95 31–95 25 27 35 31 40–40 26–95 37 42–68 41-56 70 45 25 25 27	23 23 23 25 26 230 345 34-250 56-340 236 230 25 4-3 56-340 345 34-250 56-340 2678 5 18	4 4 247 247 378 37 4 7 6–6 7–7 7 6–6 7–7 7 6–6 7–7 5 27
1D5 1D5GP 1D7 Tests 1-2 1D8 Tests 1-2 1D8 Test 3 1E3 1E4 1E5 1E7 Tests 1-2 1E8 (Adapt BW) 1F4 1F5 1F6 Tests 1-2 1F6 Test 3 1F7 (1F7GV) 1F7 Tests 2-3 1G4 1G5 1G6 Tests 1-2	2 2 1-1 2-2 1 3 2 2 1 1 1 1 1 1 1 1 1 2	2 2 2 1.4 1.4 1.4 1.4 2 2 1.4 2 2 2 2 2 2 1.4	39 33 31–95 48–37 95 30 45 35 30–30 70 47 36 37–95 95 35 95–95 30 39 35–35	340 340 56–340 60–345 8 18 35 340 348–568 2678 234 345 230–4 5 360 5–4 35 345 345 345	7 7 7 7-7 7 7 35 7 7-7 5 5 7 6-6 6 7 7-7 7

TUBE TYPE	A Cir	NOBS B Fil	C Load	LEVER I	POSITION Down
1H4 1H5 Tests 1-2 1H6 Tests 1-2 1H6 Test 3 1J5 1J6 Tests 1-2 1LA4 1LA6 Tests 1-2	1-1 1-1 2 2-2 2 1-1	1.4 2 2 2 2 1.4 1.4	30–40 40 38 39–39 40 30–95	30-5 36-5 4 345 34-56 236 34-256	7-7 7 7 7-7 8
1LB4	2 1 1-1 1-1 Good= 2	1.4 1.4 1.4 1.4 20 on	32–95 Test 2)	236 2346 34–256 236–4	8-8
1LN5 1N5 1N6 Tests 1-2	Good= 2 1 2-1	20 on 1.4 1.4 1.4	Test 2 40 27 38–95	2346 340 345–6	58
1Q5 1SA6 1SB6 Tests 1-2 1V (KR-1) 2A3 2A4 Tests 1-2	2 2 1-1 3 3 3-3	1.4 1.4 6.3 2.5 2.5	33 30 36–90 24 28 25–25	345 3468 348–5 2 23	7 7 7-7 34
2A5 (KR-25) 2A6 Tests 1-2 2A7 Tests 1-2 2B7 Test 1-2 2B7 Test 3 2C22	3 3-1 1 2-2 3-1	2.5 2.5 2.5 2.5	40 32–64 47–40	3 5-2340 230-5	56 56-56 56 67-67 67-67 78
2C22 (Sh 2C26 2E5 2E5 Eye CL-OP 2E22 2E24 (In Short Tes	ort Top . 3 . 2 . 4-4 . 3 . 3	6.3 2.5 2.5 6.3 2.5	35 44 0-0 25 22	0 23 24-4 2340 350	78 56 356–2356 5
short w 2E25 2E26 □ 2E30 2E31	hen mo . 3 . 3	6.3 6.3 2.5 1.4	28 21 26 70	4580 350 1256 124	2 1246 34 3

TUBE	A Cir	NOBS B Fil	C	LEVER PO U Up	OSITION D Down
2E32 2E35 2E36 2E41 2E42 2S/4S (G-2) 2S/4S Test 2 2V3 (Good=20) 2W3 2Z2 (G84) 3B5* 3B7 (1291) 3B7 Test 2 3D6 (1299) 3LE4 3LF4* 3Q4* 3Q5* 4A6 Tests 1-2 10 10Y 12A 12A5 12A6 12A7 Tests 1-2 12B8 Tests 1-2 12C8 Tests 1-2	3-3 3-3 3 2-2 2	1.4 1.4 1.4 1.4 1.4 1.4 1.4 1.4 1.4 1.4	70 75 75 77 77 77 45 45 96 36 56 35 33 30 34 30 33 27 35–46 42 26 32 32 29–20 30–30 26–26 41–38 38 20–22 25 36 40 31 37–39 48 56 32 32 32 32 31 31 31 31 31 31 31 31 31 31 31 31 31	124 124 124 1235 1235 1235 3 2 0 4 2 345 236 236 236 236 236 236 236 236 236 236	3 3 3 4 4 4 45 45 7 8 4 27 18 18 18 18 18 18 18 18 17 27 8 8 4 4 4 5 6 7 8 7 8 7 8 7 8 7 8 7 8 7 8 7 8 7 8 7

TUBE	A	NOBS B C Fil Load	LEVER PO U Up	DSITION DOWN
86M		6.3 37	35	78
87S	2 3	6.3 33 6.3 31	230 340	45 6 5 7 8
88 Tests 1-2		5 26–26		4-4
88S	3	6 3 32	230	456
89	3	6.3 32 6.3 32	230	56
95	3	4.5 30	234	56
98 Tests 1-2	3–3	6.3 26–26	2–3 23	45-45
99 (99X X99) 99V/V99	2	2.5 65 2.5 65	13	4
9001 🗆	2	2.5 65 6.3 20 6.3 27 6.3 27	156	247
9002 🗆	2	6.3 27	156	247
9003 🗆	2	6.3 27	156	247
9006 🗆		6.3 25	15	247
AF Tests 1-2 AG Tests 1-2	3–3	2.5 24-24 5 26-26		4-4
G-4 Tests 1-2	1-1	2.5 45-45		45-45
GA	3	5 32	234	5
PZ	3	2.5 41	234	5
PZH	. 3	2.5 36		56
R-30	. 2	2 35	23	4
R-100	3	7.5 43	0	4
RK-33 Tests 1-2	3–3	Caps Toge 6.3 27-27	45-30	67-27
RK-34		6.3 27	50	47
	ap Lead	on Left T		
RK-34 Test 2	. 3	6.3 27	30	47
		on Right T		
RK61	. 0	1.4 77 2.5 59	13	2
WL-481	4	2.5 59 1.4 55	23	4
WND. A	3	6.3 35	23	456
WND. C	. 3	2.5 35 6.3 20 6.3 27	23	456
XXFM	1	6.3 20	23	478
XXFM Test 2	. 1	6.3 27	5	48
XXFM Test 3	. 1	6.3 27	6	78
Z2000 Tests 1-2	1-1	6.3 22–22	25-16	37-37

TUBE KNOBS LEVER POSITION
TYPE A B C U D
Cir Fil Load Up Down

The Triplett Electrical Instrument Co.

Blumon, Ohio

Printed in U.S.A.